



**Ingal Building Systems  
INGAL Lintels**


**Compliance with AS2699.3:2002**

**Search Location:**

Kellyville, NSW

**Coordinates:**

33° 42' 20" South  
150° 57' 31" East



**Salt deposition rate of Kellyville:-**

20.9mg/m<sup>2</sup>/day

**Estimated service life:-**

**300g/m<sup>2</sup>  
R2 rating**

**600 g/m<sup>2</sup>  
R3 rating**

*Lintel environment*

29 years

76 years

**Minimum durability classification:-**

**R3**

Note: The Industrial Galvanizers Corporation and CSIRO Corrosion Mapping site should be viewed in conjunction with the above information. Refer to

[www.ingal.com.au](http://www.ingal.com.au)